

DCS issues

The source of these DCS issues are the NOvA ECL entries filled in by shifters. I try to compiled them all:

1. Rack monitor for ND underground was not working
2. FD APD temperature monitor is in alarm state for FEB temperature just above 45 degrees celcius. Alarm is because of it FEB temp floats around 45C.